

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 1.** Photo taken from east of location, facing West. Well location and access road have not been reclaimed per Rule 1004. Undesirable plant species, Kochia (*Kochia scoparia*), exists throughout location with little to no native, perennial vegetative growth establishment.

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 2.** Photo taken from eastern access road, facing West. Access has not been reclaimed.

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 3.** Photo taken from associated (i.e. tank battery) location, facing West. Location has not been reclaimed per Rule 1004.

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 4.** Photo taken from associated (i.e. tank battery) location, facing East. Location has not been reclaimed per Rule 1004.

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 5.** Photo taken north of location documenting reference native, perennial vegetative plant community (e.g. Salt Meadow) that is not reflective throughout well location and associated production facilities.

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 6.** Close up photo of reference salt meadow plant community.

## Final Reclamation Inspection- Plugged and Abandoned



**Photo 7.** Aerial imagery of location using COGCC GISOnline. Need to reclaim well location, associated production facilities, and access road.