

# Construction Inspection



**Photo 1.** Photo taken from southeast location, facing West. Stormwater control BMP installed in center of photo.

## Construction Inspection



**Photo 2.** Photo taken from southeast location, facing North. Stormwater control BMP installed in center of photo.

## Construction Inspection



**Photo 3.** Photo taken from northeast location, facing West. Stormwater control BMP installed in center of photo.

## Construction Inspection



**Photo 4.** Photo taken from northwest location, facing South. Stormwater control BMP installed in center of photo.

## Construction Inspection



**Photo 5.** Photo taken from western location, facing West. Stormwater control BMP installed in center of photo.

## Construction Inspection



**Photo 6.** Photo taken from southwest location, facing East. Stormwater control BMP installed in center of photo.

## Construction Inspection



**Photo 7.** Photo taken from eastern location, facing West towards topsoil stockpile. Topsoil stockpile needs to be stabilized upon completion of salvage process.

## Construction Inspection



**Photo 8.** Photo taken from southern location, facing North. Topsoil salvage in process.

## Construction Inspection



**Photo 9.** Photo taken from southwest entrance of location- culvert installed.

## Construction Inspection



**Photo 10.** Photo taken from southeast entrance of location- culvert installed.