

## Construction Inspection



**Photo 1.** Photo taken from entrance of location, facing North.



## Construction Inspection



**Photo 2.** Photo taken from entrance location, facing East. Stormwater control BMP installed in center of photo.



## Construction Inspection



**Photo 3.** Photo taken from southwest corner, facing North. Stormwater control BMP installed in center of photo.



## Construction Inspection



**Photo 4.** Photo taken from northeast corner, facing West. Stormwater control BMP installed in center of photo.



## Construction Inspection



**Photo 5.** Photo taken from eastern location, facing West. Topsoil stockpile located on northern location.