



photo 1: Facing south along the access road.



photo 2: Facing southwest along the access road.



photo 3: Facing southwest toward the location.



photo 4: Southwest side facing northeast. Soils appear to have been one direction. Dirt clods remain along the surface.



photo 5: West side of the location facing east.



photo 6: North side of the location facing south.



photo 7: Northeast side facing southwest.



photo 8: Facing west at the surrounding undisturbed vegetation.