



photo 1: West side of the location facing east.



photo 2: Northwest corner facing east. All four guy line anchors are present.



photo 3: Southeast guy line anchor.



photo 4: Cement and a wood 2x4 debris noticed at the east side of the location.



photo 5: Soils at the location seem to be compacted. The shovel could not penetrate the surface.



photo 6: View of area that seemed to have compacted soil. No vegetation growth noticed possibly due to compaction.