



photo 1: Facing west along the access road. A diversion ditch with rock rip/rap has been installed.



photo 2: A diversion ditch with rock rip/rap has been installed to direct stormwater away from the main access road.



photo 3: Sediment has been cleaned out of the cattle guard.



photo 4: Facing west along the access road.



photo 5: Northeast side of the location facing southwest.



photo 6: Area near well head where oil stained surface was noticed appears to have been cleaned up.



photo 7: Southeast side of the location facing west.



photo 8: Noticed Bull thistle beginning to germinate at the southeast side of the location.