



photo 1: Facing west toward the access road from the county road.



photo 2: Sediment around the culvert has been removed.



photo 3: Facing west toward the access road.



photo 4: Facing northwest toward location. Diversion ditch around the west side of the location.



photo 5: Facing toward the cut slope at the west side of the location. Vegetation is not established along this area of the pad.



photo 6: Door of the shed is broken.



photo 7: Northeast side of the location facing west.



photo 8: Northeast side of the location facing south. Vegetation is not established along this area of the pad.