



Photo 1. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 2. View of the project area from the northeastern corner facing center.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward. Stormwater is diverted into the culvert and off of the northeastern corner toward a drainage.



Photo 4. View of the armored drainage for diverted flows off of the well pad. This will need to be carefully monitored to ensure stabilization.



Photo 5. View of the western portion of the project area from the northwestern corner facing southward. Interim reclamation area appears to have been recontoured, decompacted, seeded and mulched with crimped straw. It is surrounded by and irrigated pasture.



Photo 6. View of the southern portion of the project area from the southwestern corner facing eastward.