



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Interim reclamation has commenced and outer portions of the well pad have been recontoured, decompacted, straw mulch crimped, and likely seeded.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 4. View of wattles and stormwater diversion in the northwestern edge of the working area and the interim reclamation area.



Photo 5. View of the western portion of the project area from the northwestern corner facing southward.



Photo 6. View of the southern portion of the project area from the well pad entrance facing westward



Photo 7. View of armored cobble run-down in the southwestern corner of the project area feeding toward culvert.



Photo 8. View of culvert outlet downstream from the project area. Does not appear that sediment has discharged from the project area at this time.