

Inspection Photos  
5/4/16  
API # 05-017-07727  
Pronghorn State 16-15-48 #1-H



Figure 1 – Lease sign at gate.



Figure 2 – Lease sign on well pad.





Figure 3 – Unused equipment stored on west side of location.



Figure 4 – Trash and stained soil on north side of pad.





Figure 5 – Trash and unused equipment on pad.



Figure 6 – Unused equipment and trash on pad.





Figure 7 – Unused equipment and trash on pad.



Figure 8 – Tank battery.





Figure 9 – Tank battery. Produced water (closest to stairs) is actively leaking.



Figure 10 – Hole in tank causing leak.





Figure 11 – Spill resulting from leak. Spill is entirely within secondary containment.



Figure 12 – Stained surface in between tanks.





Figure 13 – Stained surface off produced water tank.



Figure 14 – Stained soil off crude oil tank.





Figure 15 – Unused equipment stored on location.



Figure 16 – Wellhead and cellar.





Figure 17 – Equipment fallen over and resting on tank.