

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2016

Document Number:

675102531

Overall Inspection:

SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>283559</u>	<u>335843</u>	<u>GRANAHAN, KYLE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>100185</u>
Name of Operator:	<u>ENCANA OIL & GAS (USA) INC</u>
Address:	<u>370 17TH ST STE 1700</u>
City:	<u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Compliance Summary:

QtrQtr:	<u>NENE</u>	Sec:	<u>11</u>	Twp:	<u>4S</u>	Range:	<u>98W</u>
---------	-------------	------	-----------	------	-----------	--------	------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/29/2012	662300678	AL	AL	SATISFACTORY			No

Inspector Comment:

05-103-10712 FIGURE FOUR UNIT 8001A A11 498, 05-103-10713 FIGURE FOUR UNIT 8015C-02 A11 49, 05-103-10714 FIGURE FOUR UNIT 8001C A11 498, 05-103-10715 FIGURE FOUR UNIT 8008A A11 498, 05-103-10716 FIGURE FOUR UNIT 8002D A11 498, 05-103-10717 FIGURE FOUR UNIT 8016C-02 A11 49 - Do not appear to have been drilled - wells have form 4's stating AL status - Location ID 335843 has2 active wells present.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
268488	WELL	PR	11/19/2007	GW	103-10340	FIGURE FOUR UNIT 8002B A11 498	PR	<input type="checkbox"/>
283559	WELL	AL	04/15/2010	LO	103-10712	FIGURE FOUR UNIT 8001A A11 498	ND	<input checked="" type="checkbox"/>
283560	WELL	AL	04/15/2010	LO	103-10713	FIGURE FOUR UNIT 8015C-02 A11 49	ND	<input checked="" type="checkbox"/>
283561	WELL	PR	01/16/2007	GW	103-10711	FIGURE FOUR UNIT 8007D A11 498	PR	<input type="checkbox"/>
283562	WELL	AL	04/15/2010	LO	103-10714	FIGURE FOUR UNIT 8001C A11 498	ND	<input checked="" type="checkbox"/>
283563	WELL	AL	04/15/2010	LO	103-10715	FIGURE FOUR UNIT 8008A A11 498	ND	<input checked="" type="checkbox"/>
283565	WELL	AL	04/15/2010	LO	103-10716	FIGURE FOUR UNIT 8002D A11 498	ND	<input checked="" type="checkbox"/>
283566	WELL	AL	04/15/2010	LO	103-10717	FIGURE FOUR UNIT 8016C-02 A11 49	ND	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Predrill

Location ID: 283559
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
S/AR: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____
CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____
CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: <u>283559</u>	Type: <u>WELL</u>	API Number: <u>103-10712</u>	Status: <u>AL</u>	Insp. Status: <u>ND</u>
Facility ID: <u>283560</u>	Type: <u>WELL</u>	API Number: <u>103-10713</u>	Status: <u>AL</u>	Insp. Status: <u>ND</u>
Facility ID: <u>283562</u>	Type: <u>WELL</u>	API Number: <u>103-10714</u>	Status: <u>AL</u>	Insp. Status: <u>ND</u>
Facility ID: <u>283563</u>	Type: <u>WELL</u>	API Number: <u>103-10715</u>	Status: <u>AL</u>	Insp. Status: <u>ND</u>
Facility ID: <u>283565</u>	Type: <u>WELL</u>	API Number: <u>103-10716</u>	Status: <u>AL</u>	Insp. Status: <u>ND</u>
Facility ID: <u>283566</u>	Type: <u>WELL</u>	API Number: <u>103-10717</u>	Status: <u>AL</u>	Insp. Status: <u>ND</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____
1003a. Waste and Debris removed? _____
CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____
CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____
CM _____
CA _____ CA Date _____
Guy line anchors marked? _____
CM _____
CA _____ CA Date _____
1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: 05-103-10712 FIGURE FOUR UNIT 8001A A11 498, 05-103-10713 FIGURE FOUR UNIT 8015C-02 A11 49, 05-103-10714 FIGURE FOUR UNIT 8001C A11 498, 05-103-10715 FIGURE FOUR UNIT 8008A A11 498, 05-103-10716 FIGURE FOUR UNIT 8002D A11 498, 05-103-10717 FIGURE FOUR UNIT 8016C-02 A11 49 - Do not appear to have been drilled - wells have form 4's stating AL status - Location ID 335843 has 2 active wells present.

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation Pass

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675102532	Location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3853088