

**FORM INSP**  
Rev 05/11

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
05/11/2016  
Document Number:  
675102531  
Overall Inspection:  
SATISFACTORY

**FIELD INSPECTION FORM**

|                     |               |               |                       |                          |             |
|---------------------|---------------|---------------|-----------------------|--------------------------|-------------|
| Location Identifier | Facility ID   | Loc ID        | Inspector Name:       | On-Site Inspection       | 2A Doc Num: |
|                     | <u>283559</u> | <u>335843</u> | <u>GRANAHAN, KYLE</u> | <input type="checkbox"/> |             |

**Operator Information:**

OGCC Operator Number: 100185  
Name of Operator: ENCANA OIL & GAS (USA) INC  
Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| , Encana     |       | cogcc.inspections@encana.com |         |

**Compliance Summary:**

QtrQtr: NENE Sec: 11 Twp: 4S Range: 98W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 06/29/2012 | 662300678 | AL         | AL          | SATISFACTORY                  |          |                | No              |

**Inspector Comment:**

05-103-10712 FIGURE FOUR UNIT 8001A A11 498, 05-103-10713 FIGURE FOUR UNIT 8015C-02 A11 49, 05-103-10714 FIGURE FOUR UNIT 8001C A11 498, 05-103-10715 FIGURE FOUR UNIT 8008A A11 498, 05-103-10716 FIGURE FOUR UNIT 8002D A11 498, 05-103-10717 FIGURE FOUR UNIT 8016C-02 A11 49 - Do not appear to have been drilled - wells have form 4's stating AL status - Location ID 335843 has2 active wells present.

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                    | Insp Status |                                     |
|-------------|------|--------|-------------|------------|-----------|----------------------------------|-------------|-------------------------------------|
| 268488      | WELL | PR     | 11/19/2007  | GW         | 103-10340 | FIGURE FOUR UNIT 8002B A11 498   | PR          | <input type="checkbox"/>            |
| 283559      | WELL | AL     | 04/15/2010  | LO         | 103-10712 | FIGURE FOUR UNIT 8001A A11 498   | ND          | <input checked="" type="checkbox"/> |
| 283560      | WELL | AL     | 04/15/2010  | LO         | 103-10713 | FIGURE FOUR UNIT 8015C-02 A11 49 | ND          | <input checked="" type="checkbox"/> |
| 283561      | WELL | PR     | 01/16/2007  | GW         | 103-10711 | FIGURE FOUR UNIT 8007D A11 498   | PR          | <input type="checkbox"/>            |
| 283562      | WELL | AL     | 04/15/2010  | LO         | 103-10714 | FIGURE FOUR UNIT 8001C A11 498   | ND          | <input checked="" type="checkbox"/> |
| 283563      | WELL | AL     | 04/15/2010  | LO         | 103-10715 | FIGURE FOUR UNIT 8008A A11 498   | ND          | <input checked="" type="checkbox"/> |
| 283565      | WELL | AL     | 04/15/2010  | LO         | 103-10716 | FIGURE FOUR UNIT 8002D A11 498   | ND          | <input checked="" type="checkbox"/> |
| 283566      | WELL | AL     | 04/15/2010  | LO         | 103-10717 | FIGURE FOUR UNIT 8016C-02 A11 49 | ND          | <input checked="" type="checkbox"/> |

**Equipment:**

Location Inventory



**Predrill**

Location ID: 283559  
 Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
**S/AR:** \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_  
**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**S/AR:** \_\_\_\_\_ **Comment:** \_\_\_\_\_  
**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>283559</u> | Type: <u>WELL</u> | API Number: <u>103-10712</u> | Status: <u>AL</u> | Insp. Status: <u>ND</u> |
| Facility ID: <u>283560</u> | Type: <u>WELL</u> | API Number: <u>103-10713</u> | Status: <u>AL</u> | Insp. Status: <u>ND</u> |
| Facility ID: <u>283562</u> | Type: <u>WELL</u> | API Number: <u>103-10714</u> | Status: <u>AL</u> | Insp. Status: <u>ND</u> |
| Facility ID: <u>283563</u> | Type: <u>WELL</u> | API Number: <u>103-10715</u> | Status: <u>AL</u> | Insp. Status: <u>ND</u> |
| Facility ID: <u>283565</u> | Type: <u>WELL</u> | API Number: <u>103-10716</u> | Status: <u>AL</u> | Insp. Status: <u>ND</u> |
| Facility ID: <u>283566</u> | Type: <u>WELL</u> | API Number: <u>103-10717</u> | Status: <u>AL</u> | Insp. Status: <u>ND</u> |

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_  
Land Use: \_\_\_\_\_  
Comment: \_\_\_\_\_  
1003a. Waste and Debris removed? \_\_\_\_\_  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_  
CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_  
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: **05-103-10712 FIGURE FOUR UNIT 8001A A11 498, 05-103-10713 FIGURE FOUR UNIT 8015C-02 A11 49, 05-103-10714 FIGURE FOUR UNIT 8001C A11 498, 05-103-10715 FIGURE FOUR UNIT 8008A A11 498, 05-103-10716 FIGURE FOUR UNIT 8002D A11 498, 05-103-10717 FIGURE FOUR UNIT 8016C-02 A11 49 - Do not appear to have been drilled - wells have form 4's stating AL status - Location ID 335843 has 2 active wells present.**

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation  Pass

Well Release on Active Location

Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/A/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description         | URL   |
|--------------|---------------------|---|
| 675102531    | INSPECTION APPROVED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3853108">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3853108</a> |
| 675102532    | Location            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3853088">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3853088</a> |

