



photo 1: Noticed areas of erosion along the access road.



photo 2: Culvert appears to be filled with sediment at this area along the access road (Lat/Long:37.10380,-104.74803).



photo 3: Facing east toward the location.



photo 4: Facing toward the pit at the south side of the location. There does not seem to be an adequate berm to allow for 2 feet of freeboard.



photo 5: Facing southwest toward the pit. There does not seem to be an adequate berm to allow for 2 feet of freeboard.



photo 6: Facing toward pump jack. Exposed battery on the ground and oil stains are a potential safety concern.



photo 7: Southeast side facing northwest. Sediment trap appears to be adequate.



photo 8: Sediment trap at the northeast side, appears to be full of sediment.



photo 9: Erosion channels have developed around the north side of the location.



photo 10: Facing along the north side of the location.