



photo 1: Facing southwest toward the location.



photo 2: Facing south at cut slope side of location.



photo 3: Appears areas of the location have been reseeded and straw mulched.



photo 4: Northeast side facing west.