

## Final Reclamation Inspection



**Photo 1.** Photo taken from center of location, facing West. No evidence of wellbore or disturbance at location. Uniform vegetative plant cover throughout location.



## Final Reclamation Inspection



**Photo 2.** Photo taken from center of location, facing North. No evidence of wellbore or disturbance at location. Uniform vegetative plant cover throughout location.



## Final Reclamation Inspection



**Photo 3.** Photo taken from center of location, facing East. No evidence of wellbore or disturbance at location. Uniform vegetative plant cover throughout location.



## Final Reclamation Inspection



**Photo 4.** Photo taken from center of location, facing South. No evidence of wellbore or disturbance at location. Uniform vegetative plant cover throughout location.



## Final Reclamation Inspection



**Photo 5.** Photo taken from center of location. Birdseye view of total vegetative cover.



## Final Reclamation Inspection



**Photo 6.** Reference photo taken east of location approximately 30 meters, facing East.



## Final Reclamation Inspection



**Photo 7.** Reference photo taken east of location approximately 30 meters. Birdseye view of total vegetative cover.