

May 6, 2016 COGCC Environmental inspection of Kerr McGee Strear Farms (Facility ID: 437129)



Sign at south entrance.



Berm along access road from south entrance.



Berm along access road from south entrance.



Berm along access road from south entrance.



View looking north at land applied treatment area.



View looking east at land applied treatment area.



Concrete Liquids Handling cells.



Concrete Liquids Handling cells.



Concrete Liquids Handling cells.



Debris in Concrete Liquids Handling cells.



Concrete Liquids Handling cells.



Concrete Liquids Handling cells.



Concrete Liquids Handling cells with pallets.



Concrete Liquids Handling cells with pallets post.



Burrows in berm of cell.



Burrows in berm of cell.



Burrows in berm of cell.



Land treatment area.



Monitoring well #4 locked.



Berm along east side of facility.



Berm along east side of facility.



labeled.

300 bbl water tank not bermed, placard or properly



labeled.

300 bbl water tank not bermed, placard, or properly



Tank app 3/4 full of fluids.



Berm and fence along north boundary of Facility.



Berm and fence along north boundary of Facility.



Berm and fence along north boundary of Facility.



Monitoring Well #2 not secured.



Monitoring Well #2 not secured.



Monitoring Well #1 secured.



Berm along west side of Facility near residence.



Berm along west side Facility near residence.



Entrance at west side of the Facility.



Entrance at west side of Facility.



Fence along west side of Facility.



Fence along west side of Facility.