

Interim Reclamation Inspection



Photo 1. Photo taken of well sign for API #005-07177.

Interim Reclamation Inspection



Photo 2. Google Earth aerial imagery taken 10/9/2015 indicating approximate total disturbance of 5.0 acres. As of 5/13/16, this is the extent of the current disturbance. Form 2A (Doc. #400218050) states total disturbance of 3.67 acres and size of location after interim reclamation of 1.2 acres.

Interim Reclamation Inspection



Photo 3. Photo taken from southeast location, facing West. Overview of total disturbance illustrating unused portions of location that have not been reduced in size per Form 2A .

Interim Reclamation Inspection



Photo 4. Photo taken from northwest location, facing South. Cut slopes stabilized with soil retention blankets and mulch tackifier.

Interim Reclamation Inspection



Photo 5. Photo taken from southwest location, facing East. Cut slopes stabilized with soil retention blankets and mulch tackifier.

Interim Reclamation Inspection



Photo 6. Photo taken from northeast location, facing East. Sediment trap installed to allow sediment to settle out of stormwater runoff.

Interim Reclamation Inspection



Photo 7. Photo taken from northern location, facing North. Topsoil stockpile stabilized with soil retention blankets and the other portion of the topsoil stockpile stabilized with perennial vegetation.

Interim Reclamation Inspection



Photo 8. Photo taken from northern location, facing West. Per Rule 603.f oil and gas locations are to be kept free of serviceable equipment, vehicles, or supplies owned by the operator or any service or other third-party company performing work on behalf of the operator.

Interim Reclamation Inspection



Photo 9. Photo taken from northern location, facing West. Per Rule 603.f oil and gas locations are to be kept free of serviceable equipment, vehicles, or supplies owned by the operator or any service or other third-party company performing work on behalf of the operator.

Interim Reclamation Inspection



Photo 10. Photo taken from northern location, facing West. Per Rule 603.f oil and gas locations are to be kept free of serviceable equipment, vehicles, or supplies owned by the operator or any service or other third-party company performing work on behalf of the operator.

Interim Reclamation Inspection



Photo 11. Photo taken from northern location, facing West. Per Rule 603.f oil and gas locations are to be kept free of serviceable equipment, vehicles, or supplies owned by the operator or any service or other third-party company performing work on behalf of the operator.

Interim Reclamation Inspection



Photo 12. Photo taken from northern location, facing West. Per Rule 603.f oil and gas locations are to be kept free of serviceable equipment, vehicles, or supplies owned by the operator or any service or other third-party company performing work on behalf of the operator.

Interim Reclamation Inspection



Photo 13. Photo taken from northern location, facing West. Per Rule 603.f oil and gas locations are to be kept free of serviceable equipment, vehicles, or supplies owned by the operator or any service or other third-party company performing work on behalf of the operator.