



Photo#1: Overview of Location to North.

May 12, 2016

Inspection Photos: Bayless #081-06436



Photo#2: View to East; showing lack of Re-contouring.

Inspection Photos: Bayless #081-06436

May 12, 2016





Photo#3: Flow lines, Associated Facilities not closed, removed.

Inspection Photos: Bayless #081-06436

May 12, 2016



Photo#4: Debris left on Location.

Inspection Photos: Bayless #081-06436

May 12, 2016





Photo#5: Gravel has not been removed.

Inspection Photos: Bayless #081-06436

May 12, 2016