

## Interim Reclamation Inspection



**Photo 1.** Photo taken of well sign for API #005-07206.

## Interim Reclamation Inspection



**Photo 2.** Google Earth aerial imagery taken 10/9/2015 indicating approximate total disturbance of 5.7 acres.

## Interim Reclamation Inspection



**Photo 3.** Google Earth aerial imagery taken 10/9/2015 indicating approximate distance of 450 feet from perimeter disturbance in relation to Tebo 29-1H (005-07165) and Tebo 28-1H (005-07206).

## Interim Reclamation Inspection



**Photo 4.** Photo taken from southeast location, facing West. Overview of total disturbance illustrating unused portions of location that have not been reduced in size per Form 2A .

## Interim Reclamation Inspection



**Photo 5.** Photo taken from entrance of location, facing South. Need to maintain stormwater and sediment control BMPs.

## Interim Reclamation Inspection



**Photo 6.** Photo taken from eastern of location. Need to maintain stormwater and sediment control BMPs.

## Interim Reclamation Inspection



**Photo 7.** Photo taken from southwest location, facing South towards sediment trap. Sediment trap installed to allow sediment to settle out of stormwater runoff.

## Interim Reclamation Inspection



**Photo 8.** Photo taken from southeast location, facing South towards sediment trap. Sediment trap installed to allow sediment to settle out of stormwater runoff.

## Interim Reclamation Inspection



**Photo 9.** Photo taken from northern location, facing West. Topsoil stockpile stabilized with perennial vegetation.