

## Interim Reclamation Inspection



**Photo 1.** Photo taken of well sign for API #005-07209.

## Interim Reclamation Inspection



**Photo 2.** Google Earth aerial imagery taken 10/9/2015. Two areas of concern need to control stormwater and erosion. One area is located on the northeast well pad and the second area is approximately 800 feet south of the entrance on a pipeline.

## Interim Reclamation Inspection



**Photo 3.** Photo taken from northeast location, facing South. Need to stabilize production area and prevent erosion.

## Interim Reclamation Inspection



**Photo 4.** Photo taken from northeast location, facing Northeast towards sediment trap. Sediment trap installed to allow sediment to settle out of stormwater runoff.

## Interim Reclamation Inspection



**Photo 5.** Photo taken from Conoco Phillips pipeline ROW. Refer to Photo 2.

## Interim Reclamation Inspection



**Photo 6.** Photo taken from previous location, facing East. Need to control stormwater and erosion. Stormwater is cutting underneath wattle and transporting sediment.

## Interim Reclamation Inspection



**Photo 7.** Photo taken from previous location, facing South. Need to control stormwater and erosion. Stormwater is cutting underneath wattle and transporting sediment.

## Interim Reclamation Inspection



**Photo 8.** Photo taken from previous location, facing North. Need to control stormwater and erosion. Stormwater is cutting underneath wattle and transporting sediment.