



Photo#1: Overview of Location to SE

May 13, 2016

Inspection Photos: SWN API# 081-07737



Photo#2: Overview of Location from SE Corner; showing Large Areas no Longer needed for Use or Production that need to be Reclaimed.

May 13, 2016

Inspection Photos: SWN API# 081-07737

Photo#3:  
Drain Mid Fill Slope that needs BMPs Installed .



Photo#4:  
Drain, further South, adequately armored.



Photo#5:  
Ditch running N to S at West side of Location .



Photo#6:  
Sediment Run-Off from Pad to Ditch at SW corner



Photo#7:

Photo#8:

Erosion commencing on Cut Slope





Photo#9: Erosion Rills and Run-On to Location from Cut Slope.

May 13, 2016

Inspection Photos: SWN API# 081-07737

Photo#10:

Noxious Weed rosettes at Cut slope Area



Photo#11:

ATV Incursion into Interim Vegetation areas.

