


Photo#1:

View SE over Location.

Arrow marks site of plugging Procedures



Photo#2:

View NW over Location .




Photo#3:
View from SE Corner.



Photo#4:
View to NE from Location




Photo#5:



Photo#6:


Location receives run –off water from Gravel Pits /Irrigation.



Photo#7:

Stored O&G Equipment surrounds Location.

Photo#8:



Well Condition 5/13/2016



May 13, 2016

Inspection Photos: Vaughn Orphan API#081-05332