



Photo 1. View of recently treated musk thistle within the interim reclamation area.



Photo 2. View of un-treated, young musk thistle plants within the interim reclamation area.



Photo 3. View of stormwater diversion along the western edge of the well pad that should have stormwater controls installed per 2015 inspection.



Photo 4. Downstream view of diversion channel where it flows off of the northwestern corner of the project area and stormwater controls are needed to de-energize flows.