



photo 1: Facing southwest along fence area of the former access road.



photo 2: Facing southwest at the location.



photo 3: The area at the center of the location where subsidence was observed in the previous inspection has been regraded.



photo 4: Weed growth (Kochia) was noticed in areas of the location.



photo 5: There were areas where grass germination was noticed where the regrading occurred.



photo 6: Facing northeast toward the area which has recently been regraded.