

Construction Inspection



Photo 1. Photo taken from location entrance, facing North. Sediment control BMP installed around perimeter of location.

Construction Inspection



Photo 2. Photo taken from location entrance, facing South. Sediment control BMP installed around perimeter of location.

Construction Inspection



Photo 3. Photo taken from southwest location, facing East. Sediment control BMP installed around perimeter of location.

Construction Inspection



Photo 4. Photo taken from southeast location, facing North. Sediment control BMP installed around perimeter of location.

Construction Inspection



Photo 5. Photo taken from eastern location, facing North. Topsoil salvage in process. Need to stabilize topsoil stockpile upon completion of salvage process.

Construction Inspection



Photo 6. Photo taken from northeast location, facing West. Sediment control BMP installed around perimeter of location. Need to ensure BMPs are maintained throughout the life of the location. Silt fence will require routine maintenance, especially during construction operations.

Construction Inspection



Photo 7. Photo taken from northwest location, facing South. Sediment control BMP installed around perimeter of location. Need to ensure BMPs are maintained throughout the life of the location. Silt fence will require routine maintenance, especially during construction operations.

Construction Inspection



Photo 8. Photo taken from location entrance, facing North. Road base is currently being trucked in.

Construction Inspection



Photo 9. Photo taken from north of location, facing South. Road base is currently being trucked in.

Construction Inspection



Photo 10. Photo taken from location entrance off Hwy 60, facing West. Road base being trucked and tracking pad being built.