

Inspector: Joe MacLaren
Operator: KP Kauffman
COGCC Field Inspection Doc #: 674602591
Spill Point ID # (if applicable):

Inspection Date: 6/14/2016 (Follow up inspection)
Facility Name and Number:
Well Name and Number: UPRR PAN AM I 27
API Number (if applicable): 123 - 09913

Lube Oil Release Observed at Prime Mover



**Lube Oil Accumulations Observed Inside
Frame Rails of Pump Jack**



Inspector: Joe MacLaren
Operator: KP Kauffman
COGCC Field Inspection Doc #: 674602591
Spill Point ID # (if applicable):

Inspection Date: 6/14/2016 Follow Up Inspection)
Facility Name and Number:
Well Name and Number: UPRR PAN AM I 27
API Number (if applicable): 123 - 09913

Lube Oil Spill/ Release Observed at Wellhead



Unlabeled Container at Prime Mover



Inspector: Joe MacLaren
Operator: KP Kauffman
COGCC Field Inspection Doc #: 674602591
Spill Point ID # (if applicable):

Inspection Date: 6/14/2016
Facility Name and Number:
Well Name and Number: UPRR PAN AM I 27
API Number (if applicable): 123 - 09913

**E & P Waste Soils adjacent to excavation/
unmaintained fencing**



**Unmaintained BMP's adjacent to E & P Waste
soil pile**



Inspector: Joe MacLaren
Operator: KP Kauffman
COGCC Field Inspection Doc #: 674602591
Spill Point ID # (if applicable):

Inspection Date: 6/14/2016
Facility Name and Number:
Well Name and Number: UPRR PAN AM I 27
API Number (if applicable): 123 - 09913

Stormwater accumulation and erosion at remediation / excavation

Uncovered valve can adjacent to excavation



Inspector: Joe MacLaren
Operator: KP Kauffman
COGCC Field Inspection Doc #: 674602591
Spill Point ID # (if applicable):

Inspection Date: 6/14/2016
Facility Name and Number:
Well Name and Number: UPRR PAN AM I 27
API Number (if applicable): 123 - 09913

Free crude oil at bottom of valve can



Crude oil residue in stormwater at bottom excavation

