



Photo 1. View of the northern portion of the project area from the northeaster corner facing westward. Soil stockpiles around the working area appear to have been seeded and are revegetating along with several ruderal weeds.



Photo 2. View of the project area from then northeastern corner facing center. Northern portion of the well pad does not appear necessary for production operations.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of hoary cress (*Cardaria draba*) plants growing on the well pad.