



Photo 1. View of musk thistles (*Carduus nutans*) in the northern portion of the project area.



Photo 2. View of the western portion of the project area from the northwestern corner facing southward.



Photo 3. View of the northeastern portion of the project area from the eastern edge facing northward. Revegetation is progressing on the flat well pad surface, thin corner revegetation on soil stockpiles.



Photo 4. View of the southeastern portion of the project area from the eastern edge facing southward. Unused pipe and wood stake need to be removed.



Photo 5. View of the southern portion of the project area from the southwestern corner facing eastward. Good grass revegetation here. It appears that aspen trees were planted along southern project border.