

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2016

Document Number:

674300710

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335903	335903	Spencer, Stan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Prescott, Lorne		lprescott@laramie-energy.com	
Lujan, Carlos		carlos.lujan@state.co.us	
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Compliance Summary:QtrQtr: SWSW Sec: 17 Twp: 6S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/03/2015	674701211			ACTION REQUIRED			No
08/19/2014	674700205			SATISFACTORY			No
01/30/2014	663902735			SATISFACTORY	I		No
08/08/2013	663900223			ACTION REQUIRED	I		No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292392	WELL	PR	02/18/2011	GW	045-14709	CC 697-17-19B	PR
293501	WELL	PR	09/20/2008	GW	045-15012	CC 697-17-25B	PR
293502	WELL	PR	12/20/2008	GW	045-15013	CC 697-17-33A	PR
294084	WELL	PR	06/01/2015	GW	045-15242	CC 697-18-47B	PR
294093	WELL	PA	10/29/2014	GW	045-15244	CC 697-17-27A	PA

Inspector Name: Spencer, Stan

294095	WELL	PR	03/31/2012	GW	045-15245	CC 697-17-27B	PR	
294097	WELL	PR	08/23/2008	GW	045-15246	CC 697-17-25A	PR	
294098	WELL	PR	12/08/2008	GW	045-15247	CC 697-17-35A	PR	
294099	WELL	PR	10/01/2013	GW	045-15248	CC 697-17-35B	PR	
294100	WELL	PR	09/06/2011	GW	045-15249	CC 697-17-44	PR	
294102	WELL	PR	10/14/2008	GW	045-15250	CC 697-18-56A	PR	
294104	WELL	PR	07/01/2014	GW	045-15251	CC 697-18-64B	PR	
294107	WELL	PR	04/25/2012	GW	045-15252	CC 697-17-52	PR	
294111	WELL	PR	10/14/2008	GW	045-15253	CC 697-18-47A	PR	
294118	WELL	PR	10/11/2008	GW	045-15260	CC 697-17-33B	PR	
294119	WELL	PR	12/20/2013	GW	045-15261	CC 697-17-50	PR	
294120	WELL	PR	12/18/2008	GW	045-15262	CC 697-17-41A	PR	
294121	WELL	PR	01/21/2009	GW	045-15263	CC 697-17-41B	PR	
294194	WELL	PR	12/08/2008	GW	045-15313	CASCADE CREEK 697-19-08A	PR	
294195	WELL	PR	10/14/2008	GW	045-15314	CC 697-18-64A	PR	
294196	WELL	PR	10/14/2008	GW	045-15315	CC 697-18-39B	PR	
294362	WELL	PR	10/14/2008	GW	045-15399	CC 697-18-56B	PR	
436983	SPILL OR RELEASE	CL	04/28/2014		-	SPILL/RELEASE POINT	CL	
446050	SPILL OR RELEASE	AC	06/07/2016		-	SPILL/RELEASE POINT	AC	

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Inspector Name: Spencer, Stan

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 335903

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/AR: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/AR:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 0 Type: _____ API Number: - Status: _____ Insp. Status: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: Followup to Spill #401059359 reported on 6/8/16. Met on site with Lorne Prescott, Laramie and Carlos Lujan, COGCC. Leak resulted from a 1/4 inch hole in a ball valve on dump line between separator and tank battery. Material consisted of pw with some condensate mix. It is unknown how long the leak occurred or how much volume was lost. Dump line was excavated to 11ft bgs at which point, bedrock was encountered. Staining and odor indicated contamination at TD of excavation. Samples collected from excavation and Conn Creek ~ 650ft east of and 120ft vertical below spill.

Corrective Action: Assess nature and extent of contamination with confirmation soil samples plus Date: 07/20/2016

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: Spencer, Stan

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Guy line anchors marked? _____

CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: Spencer, Stan

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started:

Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged

Pit mouse/rat holes, cellars backfilled

Debris removed

No disturbance /Location never built

Access Roads Regraded

Contoured

Culverts removed

Gravel removed

Location and associated production facilities reclaimed

Locations, facilities, roads, recontoured

Compaction alleviation

Dust and erosion control

Non cropland: Revegetated 80%

Cropland: perennial forage

Weeds present

Subsidence

Comment:

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

S/A/V:

Corrective Date:

Comment:

CA:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300710	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3882273
674300711	Repaired ball valve in dump line	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3882208
674300712	Looking NW at spill location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3882209