

Iles Investment CO 1-23

Inspection# 673403285

No wellhead sign.



Stained soil from leak at tank base.



Stained soil from leak at tank base.



Stained soil below bucket below leak at tank loadout.



Fluid in bucket
approximately 1 inch from
overflowing.



Stained soil and fluid from
leak at tank base.



Close up of fluid at tank base.



Stained soil at tank bases.



Stained soil between tanks and pit.



Pit without net. Water and product present in pit. 2 feet of freeboard not present.



Pond adjacent to pit with multiple sheen spots observed.



Close up of one sheen spot.



Pit without netting and without 2 feet of freeboard. Drainage ditch and stream visible in background.



View of pit looking uphill towards wellhead and tanks.



Stained soil at base of tank.
No tank label.



Incomplete tank labels.

