



Photo 1. View of the project area from the southeastern corner facing center. Revegetation is progressing and is largely comprised of grazed grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*) and big sagebrush (*Artemisia tridentata*).



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward.





Photo 3. View of the southern portion of the project area from the southeastern corner facing southwestward.



Photo 4. View of tire tracks, disturbed vegetation, and pipe debris in the southern portion of the project area. Tracked portions of the interim reclamation need to be seeded and reclaimed. Pipe and other debris needs to be removed.





Photo 5. View of vehicle tracking in the western portion of the interim reclamation area that needs to be reclaimed.