



photo 1: Stormwater improvements have been performed along the access since the previous inspection.



photo 2: Sediment has been cleaned out of culvert along the access road.



photo 3: Facing toward the north side of the location.



photo 4: North side of the location facing east.



photo 5: East side of the location facing northwest.



photo 6: Facing southwest toward the pit. Sign has been placed for pit closure.



photo 7: Facing toward the south side of the location.



photo 8: Facing toward the production equipment.