

Jones 1-11

Inspection# 673403301

Stained soil at flowline connection below crude oil tank in pump jack area.



Stained soil at base of tank.



No NFPA diamond on tank.



Stained soil outside tank berm.



Stained soil at tank base.





Stained soil at loadout
outside of berm.

