



Photo 1. View of the project area from the northeastern corner facing center. Location needs interim reclamation.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. It appears that vegetated topsoil stockpile is in the northwestern corner.





Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of the western portion of the project area from the northwestern corner facing southward. It appears that old pit is being used as a large silt trap at this time.





Photo 5. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 6. View of the southwestern corner of the project area facing up-slope. Large boulders are being used to stabilize slope. Water is emerging from cut-slope.





Photo 7. View of wilted musk thistle appear to have been recently treated with herbicide.