



erosion channel seen in previous inspection filled in and bentonite muds removed from corral

06.29.2016