

Final Reclamation Inspection



Photo 1. Photo taken from center of location, facing West. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing North. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing East. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing South. No evidence of disturbance. Uniform vegetative growth throughout location.

Final Reclamation Inspection



Photo 5. Reference photo taken east of location, facing South. Location appears to be reflective of the reference area.