

Construction Inspection



Photo 1. Photo taken from southwest location, facing East. BMP installed around perimeter of location. Operator said berms will be compacted and BMP would be finished on eastern side once landowner moves equipment.

Construction Inspection



Photo 2. Photo taken from southwest location, facing North. BMP installed around perimeter of location. Operator said berms will be compacted and BMP would be finished on eastern side once landowner moves equipment.

Construction Inspection



Photo 3. Photo taken from northwest location, facing East. BMP installed around perimeter of location. Operator said berms will be compacted and BMP would be finished on eastern side once landowner moves equipment.

Construction Inspection



Photo 4. Photo taken from northern location, facing East. BMP installed around perimeter of location. Operator said berms will be compacted and BMP would be finished on eastern side once landowner moves equipment.

Construction Inspection



Photo 5. Photo taken from northern location, facing South. Topsoil salvage in process.