

Photo#1:

View SE over Location.



Photo#2:

Sediment Run-on from Crop Ground at NW Corner of Location..



Photo#3:

Drainage Containment / Pit Area?



Photo#4:

Raised Well Head / Facility Area



Photo#5:

View of Cut Slope from NE corner of Location.



Photo#6:


Fill Slope containing Run-on from Crop ground.



Photo#7:

Thistle Rosettes Emerging across Location

Photo#8:



Silver Location surrounded by Crop Ground



May 13, 2016

Inspection Photos: Silver Orphan API#081-06682