



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is established on the slope and dominated by smooth brome (*Bromus inermis*) and western wheatgrass (*Pascopyrum smithii*) with scattered forbs such as yellow clover (*Melilotus officinalis*) and yarrow (*Achillea millefolium*).



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of the southern portion of the project area from the access road entrance.



Photo 5. View of roadside ditch along access road from well pad facing toward entrance. Rock check dams are being used to de-energize flows.



Photo 6. View of culvert at the entrance to the access road that is damaged and full of sediment. Culvert needs maintenance and repair.