



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northwestern portion of the project area from the northern corner facing southwestward. Revegetation is progressing, dominated by grazed grasses and scattered sagebrush (*Artemisia tridentata*).





Photo 3. View of the eastern portion of the project area from the northern corner facing southward.



Photo 4. View of the southern portion of the project area from the southeastern edge facing westward. Stormwater flows in this portion of the well pad are diverted through black piping and armored outlet and flows from the access road are diverted along vegetated swale in background.





Photo 5. View of area where concentrated stormwater flows off of the southeastern corner of the well pad. Channel is armored and appears stabilized at this time.



Photo 6. View of unused pipe that sitting in rangeland southwest of project area that needs to be removed.





Photo 7. View of more unused pipe, southwest of the well pad that needs to be removed.



Photos 8 and 9. View of debris on the well pad that needs to be removed.