

Final Reclamation Inspection



Photo 1. Aerial imagery taken 2013 using COGCC GISOnline, illustrating areas that still have not been reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 2. Photo taken from the well location, facing North. Access road needs to be reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from the eastern entrance of the tank battery location off CR 18, facing South. Need to reclaim location per Rule 1004.

Final Reclamation Inspection



Photo 4. Photo taken from the eastern tank battery location. Equipment still remains and needs to be removed per Rule 1004.

Final Reclamation Inspection



Photo 5. Photo taken from the northern tank battery location, facing West. Need to reclaim location per Rule 1004.

Final Reclamation Inspection



Photo 6. Photo taken from the northern tank battery location, facing East. Need to reclaim location per Rule 1004.

Final Reclamation Inspection



Photo 7. Photo taken of the western entrance of the tank battery location off CR 18, facing North. Need to reclaim location per Rule 1004.

Final Reclamation Inspection



Photo 8. Photo taken of a List B Colorado Noxious weed species, (*Carduus nutans*). Needs to be removed per Rule 1004.