



photo 1: Access road near the location is showing signs of erosion.



photo 2: Facing east toward the north side of the pad.



photo 3: North side of the location facing south.



photo 4: The south slope is not stabilized and there is signs of erosion from stormwater runoff.



photo 5: Sediment is being deposited near the equipment along the south side of the location.



photo 6: Along the main access road (37.137,-104.897) there is signs of sediment migration onto the access road.