

Spetter 5-8

Inspection# 673403396

Access road overgrown and difficult to locate.




Fueling hose in foreground, no wildlife protection on exhaust in background. Storage without containment on left of separator.



No battery sign. No tank label. No berm.



List B noxious weeds in disturbed area on west of location created by erosion gully (1 of 2) seen in background. Unmarked deadmen at top of slope.



Erosion gully (2 of 2) on west side of location.



Pipe risers.

