

Federal 6-25

Inspection# 673403397

Ruts in access road.



Pump jack base on location.



Beginning of erosion gully off location.



Looking up gully back towards location.

