

Final Reclamation Inspection



Photo 1. Aerial imagery from 5/3/2006 illustrating total areas that have not been reclaimed per Rule 1004 (highlighted in red).

Final Reclamation Inspection



Photo 2. Photo taken north of tank battery location, facing West towards well location. Access road needs to be reclaimed per Rule 1004.

Final Reclamation Inspection



Photo 3. Photo taken from well location, facing West. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 4. Photo taken from well location, facing North. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 5. Photo taken from well location, facing East. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 6. Photo taken from well location, facing South. Need to reclaim location per Rule 1004. A seeding attempt was made but gravel was not removed preventing proper vegetative establishment.

Final Reclamation Inspection



Photo 7. Photo taken from well location illustrating equipment and debris that still remains and needs to be removed per Rule 1004.