

Interim Reclamation Inspection



Photo 1. Photo taken of Producing Well, API #123-39236.

Interim Reclamation Inspection



Photo 2. Photo taken from northwest location, facing South. Interim reclamation areas are not representative of reference areas as illustrated in this photo. Bare soil and inconsistent growth are apparent throughout interim areas.

Interim Reclamation Inspection



Photo 3. Photo taken from northern location, facing East. Interim reclamation areas are not representative of reference areas as illustrated in this photo. Bare soil and inconsistent growth are apparent throughout interim areas.

Interim Reclamation Inspection



Photo 4. Photo measurement taken from previous photo. Crop height is about 19" in this approximate location.

Interim Reclamation Inspection



Photo 5. Reference photo taken from southwest location, illustrating crop density is much higher and crop height is much higher- refer to following photo.

Interim Reclamation Inspection



Photo 6. Photo measurement taken from previous photo. Crop height is about 36-37" in this approximate location which is not reflective of the entire interim area.