

# Stormwater Inspection

07/11/2016

Operator: Western Operating

Location ID: 435387


Washington County, CO

CNW Section 9 T1S R56W

Aaron Trujillo

Reclamation Specialist

COGCC



WESTERN OPERATING CO.  
(303) 893-2438  
BOBCAT TANK BATTERY  
SEC.9-T1S-R56W  
WASHINGTON COUNTY, CO  
HWY 71 & CR29  
3.8 MI WEST, SOUTH INTO

07.11.2016 09:56

**Figure 1:** Photo of sign taken at battery.



**Figure 2:** Photo taken from the south end of the location, facing east. Photo shows area where gully erosion had occurred had been repaired and seeded.



**Figure 3:** Photo taken from the south end of the location, facing northeast. Photo shows area where gully erosion had occurred had been repaired and seeded.



**Figure 4:** Photo taken from the south end of the location, facing north. Photo shows area where gully erosion had occurred had been repaired and seeded.



**Figure 5:** Photo taken from the east end of the location. Photo shows germination over the seeded area.



**Figure 6:** Photo taken from the east end of the location, facing north. Photo shows gully erosion beginning to reform on the right of the photo.



**Figure 7:** Photo taken from the east end of the location, facing west. Photo shows erosion occurring over the reclamation area.



**Figure 8:** Photo taken from the east end of the location, facing west. Photo shows erosion occurring over the reclamation area. Note rock/gravel bottom of photo was transported via stormwater from battery location



**Figure 9:** Photo taken from the east end of the location, facing west. Photo shows erosion occurring over the reclamation area. White hard hat used for reference.



**Figure 10:** Photo taken from the east end of the location, facing east. Photo shows erosion occurring over the reclamation area.



**Figure 11:** Photo taken from the south end of the pit location, facing east. Photo shows berm has been reworked, stormwater and sediment ditch constructed.



**Figure 12:** Photo taken from the south end of the pit location, facing east. Photo shows berm has been reworked.



**Figure 13:** Photo taken from access road on the west end of the location. Photo shows stormwater diversion ditch constructed on the south end of the location.

**Figure 14:**

**Figure 15:**

**Figure 16:**

**Figure 17:**