

Construction Inspection

07/12/2016

Operator: Grand Mesa Operating

Location ID: 446515

Washington County, CO

SWNE Section 25 T5S R54W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from CR U, facing west towards location. Access road has not been constructed.



Figure 2: Photo taken from the east end of the location, facing west. Photo shows entrance to location. Note vehicle tracking BMPs absent.



Figure 3: Photo taken from the east end of the location. Photo shows perimeter berms have been constructed improperly; berms along perimeter are not compacted and have either been incorrectly tracked, or not tracked at all.



Figure 4: Photo taken from the southeast corner of the location, facing north. Photo shows berms have not been constructed properly; berms along perimeter are not compacted and have either been incorrectly tracked, or not tracked at all.



Figure 5: Photo taken from the southeast corner of the location, facing west. Photo shows berms have not been constructed properly; berms along perimeter are not compacted and have either been incorrectly tracked, or not tracked at all.



Figure 6: Photo taken from the southwest corner of the location, facing east. Photo shows portion of the topsoil pile. No stormwater or sediment control BMPs in place.



Figure 7: Photo taken from the southwest corner of the location, facing north. Photo shows portion of the topsoil pile. No stormwater or sediment control BMPs in place.



Figure 8: Photo taken from the northwest corner of the location, facing south. Photo shows portion of the topsoil pile. No stormwater or sediment control BMPs in place.



Figure 9: Photo taken from the northwest corner of the location, facing east. Photo shows no stormwater or sediment control BMPs in place.



Figure 10: Photo taken from the north end of the location, facing east. Photo shows berms have not been constructed properly; berms along perimeter are not compacted and have either been incorrectly tracked, or not tracked at all.



Figure 11: Photo taken from the northeast end of the location, facing west. Photo shows berms have not been constructed properly; berms along perimeter are not compacted and have either been incorrectly tracked, or not tracked at all.



Figure 12: Photo taken from the northeast end of the location, facing south. Photo shows berms have not been constructed properly; berms along perimeter are not compacted and have either been incorrectly tracked, or not tracked at all.



Figure 13: Photo shows perimeter berms have been constructed improperly; berm has been improperly tracked.