



**photo 1:** Facing toward the beginning of the access road.



**photo 2:** Facing northwest along the access road. The access road has not been reclaimed and there is noxious weed infestation along the road.





**photo 3:** There is Diffuse and Spotted knapweed (List B noxious weeds) growing along the access road and at the location.



**photo 4:** A plastic culvert and gravel remains along the access road.





**photo 5:** Facing northwest toward the location.



**photo 6:** Northwest side of the location facing northeast.





**photo 7:** North side of the location facing south. Gravel remains in this area where there is less vegetation establishment.



**photo 8:** Facing along the northwest side of the location.





**photo 9:** There is a Russian olive tree which is a List B noxious weed growing at the northwest side of the location.



**photo 10:** There is Diffuse and Spotted knapweed growing at the location which is beginning to produce seed.





**photo 11:** An electrical utility remains at the southeast side of the location.



**photo 12:** An electrical utility remains along the access road.