

Final Reclamation Inspection- Pit



Photo 1. Photo taken from the eastern skim and produced water pit location, facing Northwest. Reclamation is IN PROCESS and will be evaluated on a future date to ensure compliance with Rule 1004.

Final Reclamation Inspection- Pit



Photo 2. Photo taken from the eastern skim and produced water pit location, facing Southwest. Reclamation is IN PROCESS and will be evaluated on a future date to ensure compliance with Rule 1004.

Final Reclamation Inspection- Pit



Photo 3. Photo taken from the eastern skim and produced water pit location, facing West. Reclamation is IN PROCESS and will be evaluated on a future date to ensure compliance with Rule 1004.